

# Air Leakage Test Report

Prepared by Robert Simpson, Certified Energy Advisor

Reference Number: xxxxxxx

Date: 14 January 2010

Client Name: D. Client

Civic Address: 4 Daor Road, Ottawa, ON

## Test Results

Air changes per hour (ACH) @ 50 Pa ACH = air changes per hour	10.07 ACH
Equivalent Leakage Area (EqLA)	1613.4 cm <sup>2</sup>

## Recommendations:

- 1) Install weatherstripping around attic hatch perimeter
- 2) Install weatherstripping around doors and windows
- 3) Seal header space in basement
- 4) Seal area around plumbing stack

Discovery Home Inspections  
T 613-295-7865

**Sample Report  
Reproduction Prohibited**